



MITSUBISHI L200 (Triton) (KA; KB; 2.4; 2.5D; 3.2D)
MITSUBISHI Pajero Sport II (KH0; 2.5TD; 3.0; 3.2TD; 3.5)

2007
2008


14.1145 V2

05/08/15

1/7





GB Location/Position Arrow

















GB Movement Arrow




GB Screw Arrow




A				1X	
B		2X	C		AT only 1X
D		M10 2X	E		2X
F	AT only 	M8x20 2X	G		M10x20 2X
H		M10x30 6X	I		1X
J	AT only 	Ø 8 2X	K		Ø 10 10X
L		2X			
14.1145 V2			05/08/15		3/7










4




5



6



7



8

